



"Your Complete Bar Solution Center"

Instruction sheet for the DFC 9500 FOB(foam on Beer) detector

Disconnect the keg coupler from the empty keg and connect to a full keg in the usual manner.
Follow the operating instructions for the DFC 9500 below. It's as easy as 1..2..3

UNTAP OLD KEG AND TAP NEW KEG



Push vent button. Wait a few seconds for foam to settle and vent again, ensuring the chamber is generally full of beer.



Twist Up Twist the knob counterclockwise until it stops! Float will rise to top of chamber.



Lock Down Twist the knob clockwise fully until it stops. That's it! You are now ready to pour beer!



Cleaning (Authorized Personnel Only)
When flushing lines, twist knob counterclockwise, until it stops in the twist up position (#2). Operate the vent button a few times while flush cleaning to ensure the vent will not "stick" in an open position during regular use.